

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2020

Submitted Date:

04/29/2020

Document Number:

699301583

FIELD INSPECTION FORM

Loc ID 317870 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 14 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240098	WELL	PR	12/05/1973	OW	123-07886	ROY DUTCHER UNIT B 1	PR

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate starting to fade and will need to be replaced in the near future		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barb wire shared with all equipment on location		
Corrective Action:		Date:	

Equipment:

Type:	Horizontal Heated Separator	# 3		corrective date
Comment:				
Corrective Action:		Date:		
Type:	Bird Protectors	# 5		
Comment:				
Corrective Action:		Date:		
Type:	Ancillary equipment	# 6		

Comment: Transformers, electric panel, meter box and automation		Date:
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Appears to be plumbed to surface		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: electric motor		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	75 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Shares containment with crude tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 240098 Type: WELL API Number: 123-07886 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 4/29/2020 at approximately 1345 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location. Roy Dutcher unit b #1 at API #05-123-07886 in Weld County Colorado. This is a follow up inspection per Doc # 699300139. While there, I observed producing wellsite and TB. Shared location with Kerr McGee TB. During this inspection the following compliance issues have been addressed: Housekeeping: Stained soil around WH, under crude oil tank valves, oil production plumbing has been removed. Housekeeping: Unused, unmarked flow line risers have been tagged. Mechanical issues: possible leak at valves on crude oil tanks appear to have been fixed. See attached photos. Location is dry, weather is cloudy. No follow up on this site inspection needs to be conducted to ensure that all Corrective action are addressed to comply with COGCC Rules. Continuing education COGCC Inspection Report Summary.</p>	revasr	04/29/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301584	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5137148