

## Inspection Photos

Location Name: MARALEX RESOURCES INC DOME USA-610S98W /9SWNW

Location ID: 312561



Photo #1092 from entrance to location



Photo #1094 Debris around wellhead.