



**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Lease road to separator and wellhead has been damaged. See attached photos.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C	Date:	07/31/2020

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Crude oil tank contents/capacity placard is illegible. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/31/2020
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Livestock fencing		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	No calibration card is present in meter.		
Corrective Action:	Measure gas per Rule 329.	Date:	07/31/2020
Type: Bird Protectors	# 2		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Separator is anchored.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Pilot is on		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:	Produced water vault is anchored.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	Crude oil tank is anchored.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 447145 Type: TANK API Number: - Status: AC Insp. Status: AO**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>  On Thursday 4/30/2020 at approximately 14:00 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Orr 33-24 Tank Battery location #447145 in Weld County, Colorado.</p> <p>While there, I observed faded crude oil tank contents/capacity placards, AKA Midstream meter calibration card was missing, damaged access lease road to wellhead and separator. During this inspection the following possible compliance issues were observed: Rule 210.d. with a corrective action date of 7/31/2020, Rule 329 with a corrective action date of 7/31/2020, Rule 1002.f.(2)C with a corrective action date of 7/31/2020.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	04/30/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697001167	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5138239">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5138239</a>