

Inspection Photos
Location Name: State 16-2
Location ID: 312919



Photo 1. Overview of location taken facing southwest.



Photo 2. Wellhead with hissing sound coming from leak.

Inspection Photos
Location Name: State 16-2
Location ID: 312919



Photo 3. Sediment migration down access road.



Photo 4. Sediment migration down access road.