

Inspection Photos
Operator: BP America
API#: 067-06547
Date: 4/28/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern edge of the working area facing northward. Hoses and other unused equipment are stored here and need to be removed.



Photo 3. View of the eastern fill slope facing northward. Revegetation is progressing in a grazed condition with grasses such as smooth brome.



Photo 4. View of the northern project area facing westward.



Photo 5. View of reference area vegetation comprised of open grass field with grasses such as smooth brome and western wheatgrass.