

Interim Reclamation and Stormwater Inspection

April 27, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 327882

Inspection Document #: 697501430

Weld County, CO

NESW Section 36 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HSR-CONLEY #11-36A
Location ID: 327882



Photo 1. Photo taken from the western location, facing Southeast. Photo illustrates desirable, perennial plant species establishment is evident throughout the interim reclamation area. Some of the desirable species observed were: *Bouteloua gracilis*, *Panicum virgatum*, *Calamovilfa longifolia*, *Thinopyrum intermedia*, *Pascopyrum smithii*, and *Dactylis glomerata*.

Inspection Photos
Location Name: HSR-CONLEY #11-36A
Location ID: 327882



Photo 2. Photo taken from the western location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: HSR-CONLEY #11-36A
Location ID: 327882



Photo 3. Photo taken from the western location, facing Northeast. See comments under Photo 1.

Inspection Photos
Location Name: HSR-CONLEY #11-36A
Location ID: 327882



Photo 4. Photo taken from the eastern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: HSR-CONLEY #11-36A
Location ID: 327882



Photo 5. Photo taken from the eastern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: HSR-CONLEY #11-36A
Location ID: 327882




Photo 6. Photo taken from the eastern location, facing North. See comments under Photo 1.