

Inspection Photos  
Location Name: NEW ELK 25-06  
API#: 05-071-09536  
INSP. #: 695102767



Colorado Oil & Gas Conservation Commission  
37.14498, -104.94908, 2342.0m, 272°  
2020/04/30 11:32:10

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission  
37.14516, -104.94863, 2329.0m, 353°  
2020/04/30 11:32:35

PHOTO 2: WELL SIGN



## Inspection Photos

Location Name: NEW ELK 25-06

API#: 05-071-09536

INSP. #: 695102767



**PHOTO 3: STANDING OIL IN COMPRESSOR SKID.  
APPEARS THAT ENGINE OIL IS BEING DRAINED INTO  
SKID. Comply with general provisions of the oil and  
gas act for wildlife protection. CA DATE 5-7-20.**



**PHOTO 4: STANDING OIL IN PRIME MOVER ENGINE SKID.  
APPEARS THAT ENGINE OIL IS BEING DRAINED INTO  
SKID. Comply with general provisions of the oil and gas act for  
wildlife protection. ENGINE SKID IS FULL OF FLUID AND  
ABOUT TO RUN OVER 24 OURS TO CORRECT CA DATE 5-1-20.**



## Inspection Photos

Location Name: NEW ELK 25-06

API#: 05-071-09536

INSP. #: 695102767



**PHOTO 5: IMPACTED SOIL NEAR AND AROUND COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. 5-7-20.**

**PHOTO 6: ANOTHER IMAGE OF IMPACTED SOIL AROUND COMPRESSOR SKID.**

## Inspection Photos

Location Name: NEW ELK 25-06

API#: 05-071-09536

INSP. #: 695102767



**PHOTO 7: IMPACTED SOIL NEAR AND AROUND  
PRIME MOVER ENGINE SKID. Conduct maintenance  
on equipment, cleanup stained material and review  
self inspection processes. 5-7-20.**

