



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PIT

Comment: ADEQUATE

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Ancillary equipment # 1

Comment: **TELEMETRY EQUIPMENT**

Corrective Action:

Date: \_\_\_\_\_

Type: Bradenhead # 1

Comment: **IS PLUMBED TO SURFACE**

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 291327 Type: WELL API Number: 071-09361 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">THIS IS A FOLLOW UP TO INSPECTION DOC#688401120. CA HAS BEEN ADDRESSED.</a>	beardsit	04/30/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695102760	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139272">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139272</a>