

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2020

Submitted Date:

05/01/2020

Document Number:

700700610

**FIELD INSPECTION FORM**Loc ID 323891 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sgghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		scollett@grizzlyenergyllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211109	WELL	PR	04/10/1997	GW	045-06868	DALEY 1	PR

**General Comment:****COGCC Inspection Report Summary**

On Friday 5/1/20 at approximately 11:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Daley 1, at Location # 323891 in Garfield Colorado.

While there, I observed normal production operations.

This is a summary of inspection report

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pig station		
Corrective Action:		Date:	

Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Type	TANK BATTERY			
Comment:				
Corrective Action:			Date:	

**Equipment:**

				corrective date
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Pig Station	# 7			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment	#			
Comment:	3 methanol tanks			
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	OTHER	STEEL AST		,	
Comment:	250 bbl tank					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	100 BBLS	STEEL AST		,	
Comment:						

Corrective Action:		Date:	
<b>Paint</b>			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Earth	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

<b>Inspected Facilities</b>				
Facility ID: 211109	Type: WELL	API Number: 045-06868	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	producing			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Ditches				
Ditches		Culverts				
Culverts		Gravel				
Berms		Check Dams				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700615	Photos for Daley 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139880">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139880</a>