

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



Photo 5: Photo taken from north end of the location, facing south. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established on the location/access road.



Photo 6: Photo taken from the northwest end of the location, facing south. See comments under photo 5.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



Photo 7: Continued from photo 6.



Photo 8: Photo taken from the east end of the location, facing south. See comments under photo 5.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361




Photo 9: Photo taken from the south end of the location, facing west. See comments under photo 5.



Photo 10: Photo taken from the south end of the location, facing northwest. See comments under photo 5.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



Photo 11: Photo taken from the interim areas of the location. Photo shows Diffuse Knapweed



Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 455471



Photo 5: Photo of the excavated area on the east end of the location. Photo shows soils on location.



Photo 6: Photo taken from the east end of the location. Photo shows Diffuse Knapweed remains on the location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 455471



Photo 3: Photo shows noxious weeds (Diffuse Knapweed) remaining on location.



Photo 4: See comments under photo 3

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 330359



Photo 3: Photo shows areas where stormwater from the access road is discharging onto the adjacent lands. Sediment deposition evident.



Photo 4: Photo taken from the access road. Photo shows what appear to be Canada thistle is establishing on location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 330359



Photo 5: Photo shows bindweed on access road.



Photo 6: Photo taken from the southwest end of the location. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established on the location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 330359



Photo 7: Photo taken from the southwest end of the location. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established on the location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 447525



Photo 3: Photo taken from the location, facing northwest. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established on the location. Sufficient and on-going weed management does not appear to be occurring.



Photo 4: Photo shows Diffuse Knapweed on location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 323773



Photo 1: Photo taken from the north end of the location, facing south. Photo shows stormwater ponding around well and location.




Photo 2: Photo shows noxious weeds (Diffuse Knapweed) remaining on location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 323773



Photo 3: Photo shows noxious weeds (Diffuse Knapweed) remaining on location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



Photo 1: Photo taken from north end of the location, facing south. Photo shows well and location.



Photo 2: Photo taken from the west end of the location. Photo shows Diffuse Knapweed maturing on location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 330509



Photo 3: Photo taken from the location. Photo shows Diffuse Knapweed maturing on location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327558



Photo 1: Photo taken from north end of the location, facing south. Photo provides an overview of the location. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established on the location/access road. Operator has failed to conduct sufficient ongoing noxious weed management on the location.




Photo 2: Photo taken from east end of the location, facing southwest. See comments under photo 1.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327558



Photo 3: Photo taken from south end of the location, facing southwest. See comments under photo 1.



Photo 4: Photo taken from the access road, facing north. See comments under photo 1