

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/30/2020

Submitted Date:

05/02/2020

Document Number:

688307754

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
320685 \_\_\_\_\_ Sherman, Susan \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	<a href="#">All Inspections</a>
Condill, JB	303-680-4725	jbcrog@aol.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204462	WELL	PR	08/01/2019	OW	005-06547	CHAMPLIN 126 AMOCO B 3	PR

**General Comment:**

[Annual Bradenhead Test Inspection](#)  
[Document 402131492 04 -00 -VENT\\_FLARE IN PROCESS 08/07/2019 .](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-680-4725	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type		#		corrective date
Bradenhead		# 1		
Comment:				
Corrective Action:			Date:	
Deadman # & Marked		# 4		
Comment:				
Corrective Action:			Date:	
Pump Jack		# 1		
Comment:	Stuffing box leaking (see attached photo). Not on the ground.			
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 204462 Type: WELL API Number: 005-06547 Status: PR Insp. Status: PR

**Producing Well**

Comment: [2/1/2020 production reported to COGCC database. Well SI at time of inspection.](#)

Corrective Action:

Date:

**BradenHead**

Comment: [Annual Bradenhead Test  
Bradenhead 0 psi, tubing had 30 psi and casing had 30 psi prior to test.  
Bradenhead was 0 psi for rest of test. ISIP was 0 psi. Tubing and Casing held at 30 psi for rest of test.  
Signed Form 17 is attached with inspection photos. Operator to submit Form 17 electronically to COGCC database.](#)

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688307780	Renegde Champlin 126 Amoco B 3	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5140006">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5140006</a>