

APACHE CANYON 12-06 API# 05-071-08388 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102496



PHOTO 1: MAINTENANCE WAS CONDUCTED TO THE LIQUID RING COMPRESSOR TO STOP THE OIL LEAK. THE IMPACTED SOIL/GRAVEL NEXT TO THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

APACHE CANYON 12-06 API# 05-071-08388 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102496



PHOTO 2: THE IMPACTED SOIL ON THE WELL PAD BETWEEN THE WELL HEAD AND METER HOUSE WAS CLEANED UP.

APACHE CANYON 12-06 API# 05-071-08388 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102496



PHOTO 3: THE FLUID ACCUMULATION WAS REMOVED FROM THE LIQUID RING COMPRESSOR CONTAINMENT SKID. THE IMPACTED SOIL/GRAVEL NEXT TO THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION. CONTAINMENT WAS CLEANED UP.