

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	unused equipment on location associated with tank removal replacement		
Corrective Action:	Comply with Rule 603.f		Date: 08/04/2020

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Construction orange caution fencing around excavation		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Fabricated square tubing		
Corrective Action:			Date:

Equipment:

Type: Ancillary equipment	# 2		corrective date
Comment:	Electric panel and automation		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:

Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:	Tank is on location and either in the process of being removed or it is a replacement, There is an excavation in process where the tank was in use.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 248203 Type: WELL API Number: 123-16001 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Scout card shows well as PR at the time of this inspection the well is SI, Electric panel is in the off position

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 5/4/2020 at approximately 1130 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Parker 44-15 at API #05-123-16001 in Weld County Colorado. While there, I observed SI wellsite and Out of service Tank battery. Tank is on location and either ia in the process of being removed or it is a replacement tank, There is an excavation in process where the tank was in use, see photo 4. During this inspection the following possible compliance issues were observed: 603.f Housekeeping: Unused equipment on location, CA date 8/4/2020 See attached photos 5 & 10. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	05/04/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301607	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5141138