

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2020

Submitted Date:

05/04/2020

Document Number:

699301608

**FIELD INSPECTION FORM**Loc ID 332999 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email            | Comment                         |
|--------------|-------|------------------|---------------------------------|
| ,            |       | rwatzman@kpk.com | <a href="#">All Inspections</a> |
| ,            |       | cogcc@kpk.com    | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 242238      | WELL | PR     | 02/01/2019  | GW         | 123-10029 | 1415 CORP GAS UNIT G 1 | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | Adequate |       |  |
| Corrective Action:   |          | Date: |  |

|                           |             |
|---------------------------|-------------|
| Emergency Contact Number: |             |
| Comment:                  |             |
| Corrective Action:        | Date: _____ |

|                           |                                 |                  |
|---------------------------|---------------------------------|------------------|
| <b>Good Housekeeping:</b> |                                 |                  |
| Type                      | WEEDS                           |                  |
| Comment:                  | Tumble weeds gathered around WH |                  |
| Corrective Action:        | Comply with Rule 603.f          | Date: 05/18/2020 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |  |       |
|--------------------|--|-------|
| <b>Fencing/:</b>   |  |       |
| Type               | WELLHEAD                                   |       |
| Comment:           | Barb wire                                  |       |
| Corrective Action: |  | Date: |
| Type               | PUMP JACK                                  |       |
| Comment:           | Fabricated steel pipe.                     |       |
| Corrective Action: |  | Date: |
| Type               | OTHER                                      |       |
| Comment:           | transformers, meter box and electric panel |       |
| Corrective Action: |  | Date: |

|                           |  |       |                 |
|---------------------------|--|-------|-----------------|
| <b>Equipment:</b>         |  |       | corrective date |
| Type: Prime Mover         | # 1  |       |                 |
| Comment:                  | electric motor                             |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Bradenhead          | # 1  |       |                 |
| Comment:                  | Appears to be plumbed to surface           |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Ancillary equipment | # 1  |       |                 |
| Comment:                  | transformers, meter box and electric panel |       |                 |
| Corrective Action:        |  | Date: |                 |

|                    |     |       |  |
|--------------------|-----|-------|--|
| Type: Pump Jack    | # 1 |       |  |
| Comment:           |     |       |  |
| Corrective Action: |     | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 242238 Type: WELL API Number: 123-10029 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Scout card shows well as PR at the time of this inspection the well is SI as the electric panel for PU motor is in the off position

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Monday 5/4/2020 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">14-15 Corp Gas Unit G #1 at API</p> <p>#05-123-10029 in Weld County Colorado.</p> <p>While there, I observed SI wellsite. Scout card shows well as PR at the time of this inspection the well is SI as the electric panel for PU motor is in the off position</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>603.f Housekeeping: tumble weeds around WH and PU , CA date 5/18/2020 See attached photo 2.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p> | revasr | 05/04/2020 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 699301609    | Location pics | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5141139">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5141139</a> |