

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2020

Submitted Date:

04/27/2020

Document Number:

699800986

## FIELD INSPECTION FORM

 Loc ID 312654 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num:
**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

4 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@maralexinc.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222089	WELL	SI	05/01/2012	GW	077-08691	SULFUR GULCH 9-98-10 2	SI

**General Comment:****COGCC Inspection Report Summary**

On Monday 4/27/20 at approximately 11:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW, Location #312654 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Tank capacity, contents and NFPA labels weathered and not legible. See photo #1046 with a corrective action date of 7/27/20. Multiple places with debris on location. See photo #1047, #1048 and #1050 with a corrective action date of 5/11/20. Flow line riser not LO/TO. See photo #1049 with a corrective action date of 7/27/20. MIT required on well. With a corrective action date of 7/27/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank capacity, contents and NFPA labels weathered and not legible. See photo #1046		
Corrective Action:	All tanks with a capacity of ten (10) barrels or greater shall be labeled with tank capacity, contents and NFPA labels. Properly label tank.		Date: 07/27/2020
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Flow line riser not LO/TO. See photo #1049		
Corrective Action:	Flow line risers not LO/TO or marked are considered unused equipment. Lock out tag out or plug flowline riser.		Date: 07/27/2020
Type	DEBRIS		
Comment:	Multiple places with debris on location. See photo #1047, #1048 and #1050		
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.		Date: 05/11/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Horizontal Heated Separator	# 1		corrective date

Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		,
Comment:	Capacity and contents not labeled				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 222089 Type: WELL API Number: 077-08691 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced October 2003. Last MIT preformed 9/19/14.

Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Preform MIT on well.

Date: 07/27/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Culverts				
Ditches						
		Gravel				
Berms						
		Ditches				
Gravel						
Compaction						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402382468	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134421">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134421</a>
699800987	Photos for Insp. #699800986	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134417">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134417</a>