

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/29/2020

Submitted Date:

04/29/2020

Document Number:

693502842**FIELD INSPECTION FORM**Loc ID 421202 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421206	WELL	PA	09/23/2019	OW	123-32844	SWEETGRASS 33-14	PA
421207	WELL	SI	12/01/2018	OW	123-32845	SWEETGRASS 23-14	SI
421209	WELL	PA	09/26/2019	OW	123-32846	SWEETGRASS 11-14	PA
421210	WELL	PA	09/23/2019	OW	123-32847	SWEETGRASS 12-14A	PA
421214	WELL	PA	09/23/2019	OW	123-32849	SWEETGRASS 13-14	PA
421217	WELL	SI	12/01/2018	OW	123-32852	SWEETGRASS 22-14	SI
421220	WELL	SI	12/01/2018	OW	123-32855	SWEETGRASS 14-14	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Chain link		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chain link		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment: Last meter test Date was 3-22-18			
Corrective Action: Measure gas per Rule 329.		Date: 05/29/2020	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment: Appear to be plumbed to surface			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity) 210bbl		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Shares containment with crude oil tank					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity) 315bbl		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Inspected Facilities

Facility ID: 421206 Type: WELL API Number: 123-32844 Status: PA Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: PA

Corrective Action: _____ Date: _____

Facility ID: 421207 Type: WELL API Number: 123-32845 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: According to production records Submitted to the COGCC well has not produced since 3 -1-17 no MIT on file with the COGCC, contact COGCC engineering.

Corrective Action: _____ Date: _____

Facility ID: 421209 Type: WELL API Number: 123-32846 Status: PA Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: PA

Corrective Action: _____ Date: _____

Facility ID: 421210 Type: WELL API Number: 123-32847 Status: PA Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: PA

Corrective Action: _____ Date: _____

Facility ID: 421214 Type: WELL API Number: 123-32849 Status: PA Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: PA

Corrective Action: _____ Date: _____

Facility ID: 421217 Type: WELL API Number: 123-32852 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: According to production records Submitted to the COGCC well has not produced since 3 -1-17 no MIT on file with the COGCC, contact COGCC engineering.

Corrective Action: _____ Date: _____

Facility ID: 421220 Type: WELL API Number: 123-32855 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: According to production records Submitted to the COGCC well has not produced since 3-1-17 no MIT on file with the COGCC, contact COGCC engineering.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday April 29, 2020 at approximately 11:45AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: SweetGrass #23-14</p> <p>Operator: Kerr McGee</p> <p>API#: 05-123-32845</p> <p>County: Weld</p> <p>While there, I observed a well site and production facility</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Meter test: Rule 329 c Corrective action date of 5-29-20 see photo 4</p> <p>Wells have no MIT on file with the COGCC contact engineering.</p> <p>Weather conditions: Clear and location is dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverrr	04/29/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402384754	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5136666
693502843	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5136660