

Churchill Energy, Inc - COGCC Inspection Photos

Location: Kinsman Unit 1-18

API # 123-07545 Date 5/04/2020



Incomplete signage at wellhead; view North



View of (TA) wellhead; Flowline riser removed (hole)
Domestic tap/ pressured with casing gas.

Churchill Energy, Inc - COGCC Inspection Photos

Location: Kinsman Unit 1-18

API # 123-07545 Date 5/04/2020



Close up view of domestic tap; Tied into casing, appears to be active (in service).



View south from wellhead to gas gathering meter run; area where surface equipment and tank battery has been removed by operator.

Churchill Energy Inc - COGCC Inspection Photos

Location: Kinsman Unit 1-18

API # 123-07545 Date 5/04/2020



Out of service gas gathering risers in area where production equipment (meter run) has been removed (View NE).



Production equipment and battery removed; view east from SE corner location.