

Churchill Energy, Inc - COGCC Inspection Photos
Well: Stromberger Unit 2-12
API # 123-09299 Date 5/04/2020



Incomplete signage at wellhead; view North



View of (TA) wellhead; Flowline riser removed. Valves closed; bull plugged. View NW

Churchill Energy, Inc - COGCC Inspection Photos

Well: Stromberger Unit 2-12

API # 123-09299 Date 5/04/2020



Broken master valve at wellhead.



View of (TA) wellhead; View west of location toward area where production equipment/ battery has been removed.

Churchill Energy, Inc - COGCC Inspection Photos
Well: Stromberger Unit 2-12
API # 123-09299 Date 5/04/2020



View of location from wellhead; looking North



Out of service gas meter run