

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2020

Submitted Date:

05/06/2020

Document Number:

700401334

**FIELD INSPECTION FORM**

Loc ID: 315357      Inspector Name: Moran, Rick      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74290  
 Name of Operator: RETAMCO OPERATING INC  
 Address: PO BOX 790  
 City: RED LODGE      State: MT      Zip: 59068

**Findings:**

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gose, Tom	210-216-0819	tomgose@retamco.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Glennon, Joe	406-446-1568	joeglennon@retamco.com	
Johnson, Joe	406-446-1568	joejohnson@retamco.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230693	WELL	SI	07/01/2019	GW	103-08361	PHILADELPHIA CREEK 20	SI

**General Comment:**

On 5-4-2020 inspector Rick Moran conducted a routine inspection at Retamoc Operating well Philadelphia Creek 20 in Rio Blanco county.

The following compliance issues were observed:

- 1) Gas leak at separator. Photo 6. Complete by 6-5-2020.
- 2) Trash - 5 sections of repair 15' long. Photo 7. Complete by 8-5-2020.
- 3) Signs. Update with current operator & phone number. Photo 8. Complete by 8-5-2020.

This is a summary of inspection report 700401334.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Signs. Update with current operator & phone number.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Signs. Update with current operator & phone number.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/05/2020

<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Trash - 5 sections of repair 15' long.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/05/2020

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas leak at separator. The inspector was unable to isolate where the leak is occurring. It appeared to be on the outside piping or flanges and possibly at more than one spot.		

Corrective Action: <b>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.</b>	Date: <u>06/05/2020</u>
---	-------------------------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	Open Top		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity) ~ 5 bbl		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 230693 Type: WELL API Number: 103-08361 Status: SI Insp. Status: SI

**Producing Well**

Comment: [Last recorded production June 2019. Gas could be heard moving.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: \_\_\_\_\_                      Pit ID: \_\_\_\_\_                      Lat: \_\_\_\_\_                      Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                      Liner Condition: \_\_\_\_\_

Comment: Pit next to well head without fence and possibly abandon.

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_                      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_                      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_                      Oil Accumulation: NO                      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700401335	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143669">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143669</a>