

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2020

Submitted Date:

05/06/2020

Document Number:

699301647

FIELD INSPECTION FORMLoc ID 318314 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241094	WELL	PR	08/27/1976	GW	123-08882	SUCKLA FARMS C 3	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:	empty drums by transformers		
Corrective Action:	Comply with Rule 603.f	Date:	05/20/2020
Type	WEEDS		
Comment:	Dead weeds around transformers		
Corrective Action:	Comply wit 603.f	Date:	05/20/2020

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Transformers and meter box- fabricated steel pipe		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	electric panel		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Transformers, meter box and electric panel		
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 241094 Type: WELL API Number: 123-08882 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/6/2020 at approximately 1150 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">Suckla Farms Inc. C 3 at API# 05-123-08882 in Weld County Colorado.</p> <p>While there, I observed producing wellsite.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>603.f housekeeping: Dead weeds and trash (empty drums) by the transformers, meter box and electric panel, CA date 5-20-2020 See attached photo 4.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report</p>	revasr	05/06/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301648	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143817