

Inspection Photos
Operator: BP America
API#: 067-07741
Date: 5/5/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with western wheatgrass and various wheatgrasses.



Photo 3. View of cobble placed in southwestern erosional channel. Erosion is continuing around cobble and between cobble bars, as it is not an adequate BMP in this area. Additional BMPs are needed.



Photo 4. View of cobble bare in the southwestern project area. Erosional scouring and sediment transport continuing between BMPs.



Photo 5. View of reference area comprised of pinyon-juniper woodland with sagebrush, squaw apple, western wheatgrass, and James galleta.