

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/29/2020

Submitted Date:

05/06/2020

Document Number:

692402157

FIELD INSPECTION FORMLoc ID 323879 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoil ndgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211072	WELL	PR	05/01/1994	GW	045-06830	SHAEFFER 18-5 (E18E)	RI

General Comment:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? FailComment One Anchor is not Marked.Corrective Action Mark or RemoveDate **05/27/2020**

1003b. Area no longer in use? In Production areas stabilized ? Pass1003c. Compacted areas have been cross ripped? 1003d. Drilling pit closed? Pass Subsidence over on drill pit? PassCuttings management: 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Production areas have been stabilized? Pass Segregated soils have been replaced? **RESTORATION AND REVEGETATION**CroplandTop soil replaced Recontoured Perennial forage re-established Non-CroplandTop soil replaced Recontoured Pass 80% Revegetation

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER 1003 f. Weeds Noxious weeds? P

Comment Area (aprox .25 acre) on South side of pad is not compacted or graveled and does not seem necessary for Production; re-vegetation would help with stabilization and weed control at site. Perhaps this area is being prepared for seeding; though there are no barriers to exclude traffic .

Corrective Action Inform Inspector of plans for areas not in use.Date 05/29/2020Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**Date Final Reclamation Started: Date Final Reclamation Completed: Final Land Use: Reminder: Comment: Well plugged Pit mouse/rat holes, cellars backfilled Debris removed No disturbance /Location never built Access Roads Regraded Contoured Culverts removed Gravel removed Location and associated production facilities reclaimed Locations, facilities, roads, recontoured Compaction alleviation Dust and erosion control Non cropland: Revegetated 80% Cropland: perennial forage Weeds present Subsidence

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER Comment: Corrective Action: Date

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: One area of sed migration off of Pad. Refer to Photo log attached.
 This is a drivethrough site:
 At culvert, aprox 210ft South, as access road leads out of location; there is BMP failure and resultant erosion, downgradient (SE) of culvert.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/05/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692402171	Inspection Photos RI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143887