

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2020

Submitted Date:

04/30/2020

Document Number:

699301601

**FIELD INSPECTION FORM**Loc ID 318373 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241185	WELL	SI	07/01/2019	OW	123-08973	HAZEL MCHALE 4	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Dead weeds around transformers		
Corrective Action:	Comply with 603.f	Date:	05/14/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused flowline lying next to PU		
Corrective Action:	Comply with Rule 603.f	Date:	07/30/2020
Type	OTHER		
Comment:	Stained soil by Horizontal Heated Separator		
Corrective Action:	Comply with Rule 1002..(2).D	Date:	05/05/2020

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barb wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Transformers and meter box have fabricated steel pipe.		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Flow Line	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	Electric motor				
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	appears to be plumbed to surface				
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Transformers, meter box and electric panel				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)	30 bbl				
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

  

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Shares containment with crude tank</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 241185 Type: WELL API Number: 123-08973 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

## Comment

## User

## Date

COGCC Inspection Report Summary  
 On Thursday 4/30/2020 at approximately 1420 hrs. I, Inspector Robbie Revas,  
 Conducted an on-site inspection at a KP Kauffman location:

Hazel McHale #4 at API #05-123-08973 in Weld County Colorado.

While there, I observed shut in wellsite & tank battery.  
 During this inspection the following compliance issues were observed:  
 603.f Housekeeping: unused flowline lying on the ground beside the PU. CA date 7-30-2020 see photo 5.  
 603. f housekeeping: dead weeds around transformers. CA date 5-14-2020 see photo 4.  
 1002..(2).D: Stained soil be Horizontal heated sep. CA date 5-5-2020 see TB photos 7 and 8.  
 See attached photos.  
 Location is dry, weather is cloudy.  
 A follow up on this site inspection needs to be conducted to ensure the  
 Compliance issues have been corrected to comply with COGCC rules.  
 Continuing education COGCC Inspection Report Summary.  
 This is a summary of inspection report.

revasr

04/30/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402386700	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5138257">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5138257</a>
699301602	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5138249">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5138249</a>
699301603	TB pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5138250">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5138250</a>