

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2020

Submitted Date:

04/29/2020

Document Number:

699801006

FIELD INSPECTION FORM

Loc ID 312498 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|----------------------------------|---------|
| , Engineering | | dnr_cogccengineering@state.co.us | |
| Graves, Jim | | mrinc20@maralexinc.com | |
| Jordan, Reid | | maralextechjr@gmail.com | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 221784 | WELL | SI | 01/08/1992 | GW | 077-08386 | DOME ALBERTSON 1-32 | TA |

General Comment:

[COGCC Inspection Report Summary](#)
On Wednesday 4/29/20 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at MARALEX RESOURCES INC DOME ALBERTSON-69S98W /32SEW, Location #312498 in Mesa County Colorado.

During this inspection the following possible compliance issues were observed: Multiple places with debris on location. See photo #1090 and #1091 with a corrective action date of 5/13/20. MIT required on well. With a corrective action date of 7/29/20. No pit permit on record. With a corrective action date of 5/29/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

| Location | | | |
|--|--|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Multiple places with debris on location. See photo #1090 and #1091 | | |
| Corrective Action: | Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location. | | Date: 05/13/2020 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | PIT | | |
| Comment: | Hog panels | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| | | | corrective date |
| Type: Deadman # & Marked | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Flaring: | | | |

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 221784 Type: WELL API Number: 077-08386 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced prior to 1999. Last MIT preformed on 1/28/14.

Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Preform MIT on well.

Date: 07/29/2020

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | | | | | | |
| Berms | | | | | | |
| Gravel | | | | | | |
| | | Culverts | | | | |
| Compaction | | | | | | |
| | | Compaction | | | | |
| | | Gravel | | | | |
| | | Ditches | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment: No pit permit on record.

Corrective Submit an eForm 15 Pit Report to update COGCC records with current information.

Date: 05/29/2020

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective

Date: _____

Netting:

Netting Type: Netting Condition:

Comment:

Corrective

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective

Date: _____

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| <u>All equipment has been removed from location. All that remains is the wellhead and pit.</u> | depaoloc | 04/29/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 402385503 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5137269 |
| 699801007 | Photos for Insp. #699801006 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5137265 |