

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2020

Submitted Date:

05/06/2020

Document Number:

699801054**FIELD INSPECTION FORM**Loc ID 334074 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 34720Name of Operator: GORDON ENGINEERING INCAddress: PO BOX 3525City: GRAND JUNCTION State: CO Zip: 81502**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Gordon, John	970-618-0811	johnngordon1gordon@yahoo.com	President
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221806	WELL	SI	02/01/2017	GW	077-08408	FEDERAL 32-1	TA

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 5/6/20 at approximately 14:30 hours, I, Inspector Corey De Paolo, conducted a follow up inspection at GORDON ENGINEERING INC FEDERAL-69S97W /32SWNW, Location #334074 in Mesa County Colorado.

Refer to document #699800382 inspection performed on 1/13/20. Not all corrective actions have been completed.

During this inspection the following possible compliance issues were observed: Weeds growing on location. See photo #1133 with a corrective action date of 5/20/20. Multiple holes in tank containment liner. See photo #1134 with a corrective action date of 6/16/20. MIT required on well. With a corrective action date of 8/6/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds growing on location. See photo #1133		
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all weeds from location.	Date:	05/20/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 3	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		,
Comment:	60 bbl capacity				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Multiple holes in tank containment liner. See photo #1134			
Corrective Action:	Secondary containment structures shall be sufficiently impervious to contain discharged material. Patch all hole in tank containment liner.			Date: 06/16/2020

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 221806 Type: WELL API Number: 077-08408 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Well last produced November 2016. Meter run disconnected. No MIT on record.Corrective Action: A mechanical integrity test shall be performed on each temporarily abandoned well within 30 days of temporarily abandoning the well. Preform MIT on well.Date: 08/06/2020

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Gravel						
		Ditches				
Berms						
		Gravel				
		Compaction				
		Culverts				
Ditches						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801055	Photos for Insp. #699801054	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5144146">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5144146</a>