

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2020

Submitted Date:

04/30/2020

Document Number:

693700441**FIELD INSPECTION FORM**Loc ID 415772 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neighbors, Cory		cneighbors@hpres.com	
Young, Rob		rob.young@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415983	WELL	SI	02/01/2020	OW	123-31221	Garden Creek 06-11H	EI
470406	SPILL OR RELEASE	AC	12/31/2019		-	GC 6-11H PRV release	EI

General Comment:

COGCC Enivonrmental Inspection of spill 470406. This is not a re-inspection of FIR 684905117

Inspected Facilities									
Facility ID:	415983	Type:	WELL	API Number:	123-31221	Status:	SI	Insp. Status:	EI
Facility ID:	470406	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Spills/Releases:**Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: Small spill localized beneath ECDCorrective Action: Cleanup spill and identify cause of release ECD and repairDate: 05/28/2020

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:

Comment: COGCC Environmental Inspection of Spill ID 470406 separator over pressure and PRV release. Oil spray remains on separator and ancillary electrical equipment. Road base has been removed near separator and around pipe/electrical chase and pad for control box. No soil stockpiled on location. No confirmation soil sample results received.

Corrective Action: Submit confirmation soil samples with analysis for TPH (C6-36) and BTEX from spill area on a Form 19 Supplemental Report along with root cause of separator overpressure.

Date: 05/15/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402387467	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139281
693700442	Area affected by PRV release	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139266
693700443	spill around ECD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139267