

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2020

Submitted Date:

05/08/2020

Document Number:

690005721

FIELD INSPECTION FORMLoc ID 332856 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246893	WELL	PA	12/03/2018	GW	123-14690	PLUSS L11-3	PA

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 246893 Type: WELL API Number: 123-14690 Status: PA Insp. Status: PA

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Flow line (Photo 1) and riser (Riser) improperly abandoned.
GPS data available on photos.

Corrective Action: Contact COGCC Engineering Integrity Group.

Date: 06/08/2020

COGCC Comments

Comment	User	Date
<p>On Friday, May 8, 2020 at 11:46, I, Craig Carlile conducted an on-site inspection at: COGCC location number: 332856 Operated by: Anadarco While there I observed: Improperly abandoned flow line and riser. Weather: Skies: Partly Cloudy, Wind: Calm, Temp 44 Degrees F Please contact Engineering Integrity Group to establish a plan to address the proper abandonment of the flow line and riser equipment show in the photos attached to this inspection. This is a summary of the inspection report.</p>	carlilec	05/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690005722	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145726