

Inspection Photos

API: 071-08351

Operator: TIMBER CREEK OPERATING

Inspection Date: 5/8/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08351 | Date: 5/8/2020

Inspection Photos



Photo 1. Facing southwest along the access road near the GE 31-04 site. The road has been graded and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08351 | Date: 5/8/2020

Inspection Photos



Photo 2. Facing west along the access road. The road has been graded and large rock moved off the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08351 | Date: 5/8/2020

Inspection Photos



Photo 3. The culvert inlet has been maintained and erosion repaired along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08351 | Date: 5/8/2020

Inspection Photos



Photo 4. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08351 | Date: 5/8/2020

Inspection Photos



Photo 5. The oil in the engine skid has been cleaned up.



Inspection Photos



Photo 6. The vegetation is well established in the interim area fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08351 | Date: 5/8/2020

Inspection Photos



Photo 7. Facing toward the location.

