

Investment Equipment LLC, Colorado State 1  
121-05320

Inspection #688307801

5/4/2020

Reinspection of pit spill



Colorado Oil and Gas Conservation Commission  
39.75316, -103.27171, 4803.1ft, 195°  
05/04/2020 11:40:07 AM





Colorado Oil and Gas Conservation Commission

39.75301, -103.27178, 4836.0ft, 49°

05/04/2020 11:40:33 AM



Colorado Oil and Gas Conservation Commission  
39.75304, -103.27172, 4836.0ft, 53°  
05/04/2020 11:40:20 AM





Colorado Oil and Gas Conservation Commission  
39.75145, -103.27367, 4852.4ft, 49°  
05/04/2020 11:13:59 AM





Animal holes in  
crude oil tank  
berms/maintain.

Colorado Oil and Gas Conservation Commission  
39.75147, -103.27366, 4845.8ft, 45°  
05/04/2020 11:14:06 AM





Animal hole in  
produced water  
tank  
berms/maintain.

Colorado Oil and Gas Conservation Commission  
39.75136, -103.27358, 4842.5ft, 349°  
05/04/2020 11:14:28 AM



Low spot in  
produced  
water tank  
berms on  
south side.

Colorado Oil and Gas Conservation Commission  
39.75128, -103.27334, 4875.3ft, 280°  
05/04/2020 11:19:46 AM






Colorado Oil and Gas Conservation Commission

39.75099, -103.27294, 4855.6ft, 46°

05/04/2020 11:15:45 AM

A photograph showing a body of water, possibly a reservoir or lake, with a cracked, dry shoreline in the foreground. The water is a murky greenish-brown color. The foreground shows a wide expanse of dry, cracked earth, indicating low water levels. The shoreline is uneven, with some small patches of white foam or debris near the water's edge. The background shows a distant, hilly shoreline under a clear sky.

Colorado Oil and Gas Conservation Commission

39.75095, -103.27268, 4855.6ft, 2°

05/04/2020 11:16:20 AM





Colorado Oil and Gas Conservation Commission

39.75132, -103.273, 4858.9ft, 313°

05/04/2020 11:18:22 AM





Colorado Oil and Gas Conservation Commission

39.75095, -103.27284, 4855.6ft, 154°

05/04/2020 11:16:04 AM






Area on south side of produced water pit berms where berm breached and spilled into field.

Colorado Oil and Gas Conservation Commission  
39.75095, -103.2726, 4849.1ft, 100°  
05/04/2020 11:16:29 AM





Poor vegetation  
growth on east  
side of pits  
down gradient  
from berm  
breach.

Colorado Oil and Gas Conservation Commission

39.75095, -103.27244, 4849.1ft, 39°

05/04/2020 11:16:57 AM