

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2020

Submitted Date:

05/09/2020

Document Number:

688307812

FIELD INSPECTION FORM

Loc ID 316907 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10690
Name of Operator: IMPETRO RESOURCES LLC
Address: 2820 LOGAN DRIVE
City: LOVELAND State: CO Zip: 80538

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|----------------------------|-----------------|
| Gibson, Rick | 970-768-6880 | rtgibson01@msn.com | |
| Bradley, Sam | 970-593-8626 | sbradley.impetro@gmail.com | Principal Agent |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 233114 | WELL | PR | 09/01/2015 | OW | 121-05134 | DECKER 32-18 3 | PR |

General Comment:

Routine Inspection

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-593-8626

Corrective Action: _____

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | |
|------|------|--------|--|
| | | | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|-----------|-------|--|
| Type | PUMP JACK | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | # | Comment | Corrective Action | Date | corrective date |
|--------------------|-----|----------|-------------------|------|-----------------|
| Pump Jack | # 1 | | | | |
| Prime Mover | # 1 | electric | | | |
| Deadman # & Marked | # 4 | | | | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|-----------|-------|
| Condition | _____ |
|-----------|-------|

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 233114 Type: WELL API Number: 121-05134 Status: PR Insp. Status: PR

Producing Well

Comment: [PR. 3/1/2020 production reported to COGCC database.](#)

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------------|---|
| 688307843 | Impetro Resources Decker 32-18 3 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146164 |