

Inspection Photos
Location Name: YOUNBERG 32-12
Location ID: 324061
Inspection Date: May 5, 2020



Location sign



11/12/2019 2-inch flowline penetrating the earthen secondary containment

Inspection Photos
Location Name: YOUNBERG 32-12
Location ID: 324061
Inspection Date: May 5, 2020



11/12/2019 80 bbl produced water steel AST with earthen secondary containment



11/12/2019 Stained soil located south of the wellheads



Inspection Photos
Location Name: YOUNBERG 32-12
Location ID: 324061
Inspection Date: May 5, 2020



5/5/2020 2-inch flowline penetrating the earthen secondary containment



5/5/2020 80 bbl produced water steel AST with earthen secondary containment



Inspection Photos
Location Name: YOUNBERG 32-12
Location ID: 324061
Inspection Date: May 5, 2020



5/5/2020 Stained soil located south of the wellheads

