

Inspection Photos
Operator: Enervest Operating
API#: 067-06026
Date: 5/8/2020



Photo 1. View of the project area from the northern edge facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Erosion control blanket appears to be functioning. Cut-slopes are seeded/straw-mulched in response to 2018 reclamation inspection.



Photo 3. View of erosion control blanket placed on northeastern cut-slope.



Photo 4. Birdseye view of vegetation growing within the 2018 reclaimed areas. Desirable western wheatgrass observed, as well as weedier species such as field bindweed and melilotus.



Photo 5. View of the western fill slope. Revegetation is progressing here, largely with rubber rabbitbrush, Indian ricegrass, and mixed wheatgrasses.



Photo 6. View of reference area comprised of mixed pinyon and juniper woodland, with gambel oak, mountain mahogany, sagebrush, and mixed herbaceous understory (ie: Arizona fescue, firecracker penstemon)