

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/11/2020

Submitted Date:

05/11/2020

Document Number:

696102945

FIELD INSPECTION FORM

Loc ID 329404 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 14 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249491	WELL	SI	11/01/2018	GW	123-17294	ROTH A 30-7	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Well has NOT been cut / capped.
Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID (420804).
(Well(s): 1: Shut-In | SI).

Centralized Battery formerly served 2 Location IDs (323519, 329404).
(Well(s): 2: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696102943 and/or Location ID #420804 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead: w/ Master casing valve only.		
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:	Plugged & Abandoned PA. Equipment reassigned to Loc. ID #420804.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment:	Plugged & Abandoned PA. Equipment reassigned to Loc. ID #420804.		
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment:	Plugged & Abandoned PA. Equipment reassigned to Loc. ID #420804.		
Corrective Action:			Date:

Type: Bradenhead	# 1	
Comment:	Appears plumbed to surface.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.463433,-104.590665
Comment:	<p>Centralized Battery serves 1 Location ID (420804). (Well(s): 1: Shut-In SI).</p> <p>Centralized Battery formerly served 2 Location IDs (323519, 329404). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696102943 and/or Location ID #420804 for Battery / Facility, Equipment info.</p>				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Plugged & Abandoned PA. Equipment reassigned to Loc. ID #420804.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:	Plugged & Abandoned PA. Equipment reassigned to Loc. ID #420804.				

Corrective Action:	Date:
--------------------	-------

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 249491 Type: WELL API Number: 123-17294 Status: SI Insp. Status: PA

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 05/11/2020 at approximately 12:28 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ROTH-66N64W /30SWNE Location ID: 329404 Well Name: Roth A 30-7 API: 05-123-17294 Location County: Weld County, Colorado Weather: Mostly cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Well has NOT been cut / capped. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID (420804). (Well(s): 1: Shut-In SI).</p> <p>Centralized Battery formerly served 2 Location IDs (323519, 329404). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696102943 and/or Location ID #420804 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well does NOT appear to be cut / capped. Form 42 doc. #402319352 indicates plugging start date: 02/25/2020. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/11/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102946	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5147224