

Inspection Photos

5/06/2020

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 424970

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 1: On 5/6/2020, with use of a SUA, Reclamation specialist Trujillo utilized a SUA to capture aerial imagery of the Location. Photos 1-3 were taken from the Southeast of the Location facing northwest, north and northeast. Photos provide a current overview of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 4: On 5/6/2020, Reclamation specialist Trujillo utilized a SUA to capture aerial imagery of the Location. Photo shows areas where rill erosion/erosion degradation on the southeastern slopes of the Location is evident; BMPs remain missing or insufficient. Photo also shows interim reclamation (revegetation activities) has not been completed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 5: On 5/6/2020, Reclamation specialist Trujillo utilized a SUA to capture aerial imagery of the Location. Photo shows areas on the northern end of the Location where soil replacement/contouring has been conducted (yellow). Photo also shows areas on the northern end of the Location that have not been contoured (red). Photo also shows interim reclamation (revegetation activities) has not been completed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 6: Continued from photo 5. Photo shows areas on the northern end of the Location where soil replacement/contouring has been conducted (yellow). Photo also shows areas on the northern end of the Location that have not been contoured (red). Photo also shows interim areas where BMPs appear to be missing, or insufficient, and where interim reclamation (revegetation activities) has not been completed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 7: Photo taken from the southeast end of the Location, facing northwest. Photo shows areas where rill erosion/erosion degradation on the southeastern slopes of the Location is evident; BMPs remain missing or insufficient. Photo also shows interim reclamation (revegetation activities) has not been completed. Inspector at top right of photo for reference.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 8: Continued from photo 7. Photo shows areas where rill erosion/erosion degradation on the slopes of the Location is evident; BMPs remain missing or insufficient. Photo also shows interim reclamation (revegetation activities) has not been completed. Inspector at top of photo for reference.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 9: Continued from photo 8. Photo shows sediment deposition due to erosion from the slopes.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



20200506

Photo 10: Photo taken from the slopes on the southeast end of the Location. Photo shows slopes have not been sufficiently stabilized, and/or BMPs missing or insufficient. Photo shows rocks that appear to have fallen from the slopes onto areas below the Location; Risk of rocks falling.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 11: See comments under photo 10

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 12: Photo taken from the slopes on the north end of the Location. Photo shows a crack forming along the interim areas indicating soils are unstabilized and are beginning to shift/slough.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 13: See comments under photo 12.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 424970



Photo 14: Photo taken from the topsoil stockpile on the northwest end of the Location. Photo shows soil stockpile is predominantly exposed soil, or vegetated by undesirable weedy plant species.