

# Inspection Photos

API: 071-08793

Operator: TIMBER CREEK OPERATING

Inspection Date: 5/11/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020

## Inspection Photos



**Photo 1.** There erosion near culvert inlet has been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020



## Inspection Photos



**Photo 2.** Culvert outlet protection has been installed at the culvert where erosion was observed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020



## Inspection Photos



**Photo 3.** The road has been graded where erosion was previously occurring.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020

## Inspection Photos



**Photo 4.** Culvert outlet protection has been installed at the culvert where erosion was previously observed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020



## Inspection Photos



**Photo 5.** Facing toward the culvert inlet along the main road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020



## Inspection Photos



**Photo 6.** Facing toward the access road. The erosion along the sides of the access road have been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020

## Inspection Photos



**Photo 7.** Rock wattles have been placed on the side of the access road. It is uncertain if the rock wattles will withstand the stormwater flow. These will need to be monitored and maintained to ensure stormwater does not displace or flow around.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020



## Inspection Photos



**Photo 8.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020

## Inspection Photos



**Photo 9.** The area of erosion along the road has been graded and repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020



## Inspection Photos



**Photo 10.** The culvert inlet has been cleaned out of sediment and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08793 | Date: 5/11/2020