

Inspection Photos

API: 071-09301

Operator: TIMBER CREEK OPERATING

Inspection Date: 5/11/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09301 | Date: 5/11/2020

Inspection Photos



Photo 1. Outlet protection has been installed at the culvert. It appears stormwater from the road has been directed to this area causing this erosion gully. Disturbance areas caused by erosion may need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 5/11/2020

Inspection Photos



Photo 2. Further up the road, outlet protection has been installed where erosion was during previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 5/11/2020

Inspection Photos



Photo 3. Additional rock rip/rap and check dams have been installed along the side of the road to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 5/11/2020

Inspection Photos



Photo 4. Rock rip/rap has been installed along the side of the road to prevent erosion. The culvert has been maintained and sediment cleaned out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 5/11/2020

Inspection Photos



Photo 5. Further up the main road. Rock rip/rap has been installed along the side of the road to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 5/11/2020

Inspection Photos



Photo 6. The culvert inlet has been maintained and sediment removed. Outlet protection has been installed at culvert outlet where erosion was previously observed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 7. Further up the main road toward the location. The culvert inlet has been maintained and sediment removed. Outlet protection has been installed at culvert outlet where erosion was previously observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 5/11/2020

Inspection Photos



Photo 8. This culvert along the main road has filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 5/11/2020

Inspection Photos



Photo 9. Facing toward the location. Well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09301 | Date: 5/11/2020