

Inspection Photos

API: 071-09034

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/11/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09034 | Date: 5/11/2020

Inspection Photos



Photo 1. The culvert outlet has been repaired. Additional outlet protection may be needed to prevent erosion of the diversion ditch.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 5/11/2020

Inspection Photos



Photo 2. Facing toward the culvert inlet. Additional culvert inlet protection was installed. Disturbance areas caused by erosion may need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 5/11/2020

Inspection Photos



Photo 3. The vehicle rutting along the road has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 5/11/2020

Inspection Photos



Photo 4. Rock check dams have been installed along the side of the road where erosion occurred. This will need to be monitored to ensure stormwater does not flow around the check dams causing further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 5/11/2020

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 5/11/2020