

Inspection Photos

API: 071-08508

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/11/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08508 | Date: 5/11/2020

Inspection Photos



Photo 1. The culvert along the main road has been repaired however, the culvert is filled in with sediment which will create issues.



Photo 2. The culvert was observed to be full of sediment on both ends. This culvert will likely need to be replaced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08508 | Date: 5/11/2020

Inspection Photos



Photo 3. The culvert inlets along the road leading to the location have been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08508 | Date: 5/11/2020

Inspection Photos



Photo 3. Culvert outlet protection has been installed on some of the culverts leading to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08508 | Date: 5/11/2020

Inspection Photos



Photo 4. Facing north toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08508 | Date: 5/11/2020