

Inspection Photos
Operator Name: Caerus Piceance LLC
Location: 413481



2" unmarked risers

Inspection Photos
Operator Name: Caerus Piceance LLC
Location: 413481



Flowline failure was on produced water dump line. (left side) Wells are still producing. Operator has manifold at separator and is dumping produced water and oil into one dumpline and into one tank.