

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2020

Submitted Date:

05/05/2020

Document Number:

699801038

**FIELD INSPECTION FORM**

Loc ID 323851 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
3 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 53255  
 Name of Operator: MARALEX RESOURCES INC  
 Address: P O BOX 338  
 City: IGNACIO State: CO Zip: 81137

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Graves, Jim		mrinc20@maralexinc.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210985	WELL	SI	07/01/2014	GW	045-06743	SOUTH SHALE RIDGE 10-7	SI

**General Comment:**

COGCC Inspection Report Summary  
 On Tuesday 5/5/20 at approximately 9:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /7NWSE, Location #323851 in Garfield County Colorado.  
 Refer to document #699800679 inspection conducted 3/3/20. Not all previous corrective actions have been completed. While there, I observed normal production operations.  
 During this inspection the following possible compliance issues were observed: Mechanical integrity test required on well. With a previous corrective action date of 4/3/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 210985 Type: WELL API Number: 045-06743 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced June 2014. No MIT on record.

Corrective Action: A mechanical integrity test shall be performed on each shut-in well within two years of the initial shut-in date. Preform MIT on well.

Date: 04/03/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Ditches				
		Compaction				
		Culverts				
Ditches						
		Gravel				
Berms						
Gravel						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402391232	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143174">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143174</a>
699801039	Photos for Insp. #699801038	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143168">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143168</a>