

Inspection Photos  
Operator: BP America  
API#: 067-07446  
Date: 5/12/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with grasses such as smooth brome, intermediate wheatgrass, as well as shrubby rubber rabbitbrush.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area vegetation comprised of mixed ponderosa pine woodland, opening to sagebrush shrubland, with shrubs such as river hawthorn (*Crataegus rivularis*).