

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2020

Submitted Date:

05/13/2020

Document Number:

696102961

**FIELD INSPECTION FORM**

Loc ID: 323296    Inspector Name: Evins, Bret    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
Address: 410 17TH STREET SUITE #1400  
City: DENVER    State: CO    Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245034	WELL	PA	09/11/2019	OW	123-12829	ANKENEY 2-28	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. ALL equipment has been removed.  
Reclamation progressing.  
Abandoned Battery SE corner GPS coordinates: 40.463831, -104.552973  
  
Follow-up to Field Inspection Report doc. #696300307 dated 07/08/2019.  
4 of 4 prior Corrective Action(s) appear addressed.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: Unused Equipment (Wellhead parts) at wellsite. Remove Unused Equipment (Wellhead parts) at wellsite. Comply w/ Rule 603.f. Corrective Action Date: 07/31/2019.</p> <p>This insp: * Well has been Plugged &amp; Abandoned   PA. ALL Equipment removed. Reclamation progressing. See photos #9, 10.</p>		
Corrective Action:			Date:
Type	WEEDS		
Comment:	<p>Prior insp: Weeds at Tank Battery &amp; separator areas. Control weeds at Tank Battery &amp; separator areas. Comply w/ Rule 603.f. Corrective Action Date: 07/31/2019.</p> <p>This insp: * Well has been Plugged &amp; Abandoned   PA. ALL Equipment removed. Reclamation progressing. See photos #5-8.</p>		
Corrective Action:			Date:
Type	OTHER		
Comment:	<p>Prior insp: Unmarked / Unused 1" &amp; 2" risers at wellsite. Mark and/or remove Unmarked / Unused 1" &amp; 2" risers at wellsite. Comply w/ Rule 603.f. Corrective Action Date: 07/31/2019.</p> <p>This insp: * Well has been Plugged &amp; Abandoned   PA. ALL Equipment removed. Reclamation progressing. See photos #11, 12.</p>		
Corrective Action:			Date:

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Horizontal Heated Separator	# 0		corrective date
-----------------------------------	-----	--	-----------------

Comment:	Plugged & Abandoned   PA. Battery Abandoned. ALL Equipment removed.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned   PA. Battery Abandoned. ALL Equipment removed.		
Corrective Action:		Date:	
Type: Pig Station	# 0		
Comment:	Plugged & Abandoned   PA. Battery Abandoned. ALL Equipment removed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Plugged & Abandoned   PA. Battery Abandoned. ALL Equipment removed.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				
Comment:	Plugged & Abandoned   PA. Battery Abandoned. ALL Equipment removed.				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Prior insp: Tank Berms are at an inadequate height. Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G. Corrective Action Date: 07/31/2019.  This insp: * Well has been Plugged & Abandoned   PA. ALL Equipment removed. Reclamation progressing. See photos #3, 4.			
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
------	--

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 245034 Type: WELL API Number: 123-12829 Status: PA Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 05/13/2020 at approximately 12:19 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: ANKENEY /2-28 Pad  Location ID: 323296  Well Name: Ankeney 2-28  API: 05-123-12829  Location County: Weld County, Colorado  Weather: Partly cloudy, dry.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Battery: Abandoned. ALL equipment has been removed.  Reclamation progressing.  Abandoned Battery SE corner GPS coordinates: 40.463831, -104.552973</p> <p>Follow-up to Field Inspection Report doc. #696300307 dated 07/08/2019.  During this inspection, the following prior possible compliance issues appear to be addressed:</p> <p>1.) Tank Berms are at an inadequate height.  Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G.  Corrective Action Date: 07/31/2019.  * Well has been Plugged &amp; Abandoned   PA. ALL Equipment removed.  Reclamation progressing.  See photos #3, 4.</p> <p>2.) Weeds at Tank Battery &amp; separator areas.  Control weeds at Tank Battery &amp; separator areas. Comply w/ Rule 603.f.  Corrective Action Date: 07/31/2019.  * Well has been Plugged &amp; Abandoned   PA. ALL Equipment removed.  Reclamation progressing.  See photos #5-8.</p> <p>3.) Unused Equipment (Wellhead parts) at wellsite.  Remove Unused Equipment (Wellhead parts) at wellsite. Comply w/ Rule 603.f.  Corrective Action Date: 07/31/2019.  * Well has been Plugged &amp; Abandoned   PA. ALL Equipment removed.  Reclamation progressing.  See photos #9, 10.</p> <p>4.) Unmarked / Unused 1" &amp; 2" risers at wellsite.  Mark and/or remove Unmarked / Unused 1" &amp; 2" risers at wellsite. Comply w/ Rule 603.f.  Corrective Action Date: 07/31/2019.  * Well has been Plugged &amp; Abandoned   PA. ALL Equipment removed.  Reclamation progressing.  See photos #11, 12.</p> <p>WELL STATUS COMMENT:  Plugged &amp; Abandoned   PA.  Well appears to be cut / capped.  Form 6 doc. #402178781 indicates plugging, cut/cap date: 09/11/2019. Approved.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/13/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102962	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5149727">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5149727</a>