

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /29SWNW

Location ID: 312424



Photo #1165 from entrance to location



Photo #1170 Flow line riser not LO/TO.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /29SWNW

Location ID: 312424



Photo #1166 Unused meter run.



Photo #1168 Multiple unmarked deadman.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /29SWNW

Location ID: 312424



Photo #1169 Multiple unmarked deadman.