

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #1174 from entrance to location




Photo #0334 from inspection #699800295 inspection conducted on 12/31/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #1173 Access road has not been adequately maintained.



Photo #0329 from inspection #699800295 inspection conducted on 12/31/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #1175 Tank label and placards are weathered and not legible.



Photo #0333 from inspection #699800295 inspection conducted on 12/31/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #1179 Tank by wellhead is not properly labeled.



Photo #0330 from inspection #699800295 inspection conducted on 12/31/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #1176 weeds and debris inside tank containment.



Photo #0331 from inspection #699800295 inspection conducted on 12/31/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #1177 Multiple places with weeds and debris on location.