

Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490



Location sign off of Hwy 14. (Note: phone number was not active on 9/3/2019 and has not changed since).



Well sign. (Note: phone number was not active on 9/3/2019 and has not changes since then).

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Equipment stored on Location.



Equipment stored on Location.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Propane tank not labeled or placard.



Tank signage, labels, and placards are illegible.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Tank signage, labels, and placards are illegible.



Tank 0030, staining beneath hammer unions.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Tank 0030, staining beneath hammer unions.



Valve with handle not blind plugged. Note: There was evidence of livestock accessing Facility.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Trash through out Location.



Trash through out Location.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Well head.



Pressure on gauge.