

Inspection Photos  
Operator: BP America  
API#: 067-08649  
Date: 5/12/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with grasses such as intermediate wheatgrass, crested wheatgrass, and western wheatgrass.



Photo 3. View of erosional channel approximately 2 feet wide and deep in the southern project area (facing upstream). Hard hat in place for scale.



Photo 4. View of erosional channel approximately 2 feet wide and deep in the southern project area (facing downstream). Hard hat in place for scale.



Photo 5. View of reference area vegetation comprised of open grass field with mixed native grasses such as western wheatgrass, or non-native grass such as crested wheatgrass.