

Inspection Photos  
Operator: BP America  
API#: 067-07068  
Date: 5/12/2020



Photo 1. View of the project area from the southeastern corner facing center.





Photo 2. View of the southern project area from the southeastern corner facing southwestward. An approximately 20-foot deep arroyo runs along the southern edge of the project area.





Photo 3. View of erosional head-cut in the southwestern project area (facing upstream). Hard hat in place for scale.





Photo 4. View of erosional head-cut in Photo 3, facing downstream. Stabilization is needed here.





Photo 5. View of musk thistles observed within the interim reclamation area. Approximately 200 individuals observed.





Photo 6. View of reference area vegetation (beyond fence) comprised of sagebrush shrubland with grasses such as blue grama and sand dropseed.