

Inspection Photos  
Operator: BP America  
API#: 067-09076  
Date: 5/12/2020



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with grasses such as western wheatgrass.





Photo 3. View of dense musk thistles within the western project area. Approximately 300 individuals observed.





Photo 4. View of stormwater BMP in the northern project area, that is full of sediment.





Photo 5. View of wattle and cobble BMPs in the southern project area. Large gap and headcut present beneath the wattle. Improved BMPs are needed here.





Photo 6. View of reference area vegetation comprised of sagebrush shrubland with grasses such as western wheatgrass, and sand dropseed, in a mosaic with gambel oak and Ponderosa pine woodland.