

**Inspection Photos**

**Location Name: South Leverich 13-09 Pad**

**Location ID: 335045 & Spill/Release ID: 476157**

**Inspection Date: May 5, 2020**



## Inspection Photos

Location Name: South Leverich 13-09 Pad

Location ID: 335045 & Spill/Release ID: 476157

Inspection Date: May 5, 2020



Location sign



Overview of the location, three excavations were observed at time of inspection



## Inspection Photos

Location Name: South Leverich 13-09 Pad

Location ID: 335045 & Spill/Release ID: 476157

Inspection Date: May 5, 2020



**View of the excavation on the northeast corner of the location where the spill/release occurred. A detectable hydrocarbon odor was present at time of inspection.**



**View of the excavation on the northeast corner of the location where the spill/release occurred. A detectable hydrocarbon odor was present at time of inspection.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: South Leverich 13-09 Pad

Location ID: 335045 & Spill/Release ID: 476157

Inspection Date: May 5, 2020



Excavation adjacent to the tank battery



Excavation adjacent to the tank battery



## Inspection Photos

Location Name: South Leverich 13-09 Pad

Location ID: 335045 & Spill/Release ID: 476157

Inspection Date: May 5, 2020



Excavation adjacent to the separators



Excavation adjacent to the separators



## Inspection Photos

Location Name: South Leverich 13-09 Pad

Location ID: 335045 & Spill/Release ID: 476157

Inspection Date: May 5, 2020



Hole in tank battery secondary containment liner



Hole in tank battery secondary containment liner



## Inspection Photos

Location Name: South Leverich 13-09 Pad

Location ID: 335045 & Spill/Release ID: 476157

Inspection Date: May 5, 2020



**Hole in tank battery secondary containment liner**



**Looking northeast from the location towards Beaver Creek**

