

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2020

Submitted Date:

05/15/2020

Document Number:

690101862

**FIELD INSPECTION FORM**

Loc ID 332677 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246250	WELL	PA	03/09/2016	GW	123-14047	BERNHARDT-PM O 12-03	PA
293355	WELL	SI	10/01/2016	GW	123-26525	BERNHARDT O 12-19	TA
448359	TANK BATTERY	AC	11/15/2016		-	BERNHARDT O 12-19 BATTERY	EG

**General Comment:**

Engineering Integrity Inspection; Flowline Only.  
Photos Uploaded.

**Inspected Facilities**

Facility ID: 246250 Type: WELL API Number: 123-14047 Status: PA Insp. Status: PA

Facility ID: 293355 Type: WELL API Number: 123-26525 Status: SI Insp. Status: TA

Facility ID: 448359 Type: TANK API Number: - Status: AC Insp. Status: EG

**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Noble contractors on site are in the process of removing equipment, tanks and on location flowlines at facility/ battery. COGCC form 42 Flowline Pre Abandonment - 30-day notice Doc #402317026 was received on 2/19/2020. COGCC form 44 (off location flowline abandonment) notice Doc #402358341 was received on 03/31/2020. The off location flowline between (TA/ Bernhardt O 12-19) wellhead and battery has been marked (pin flagged). No corrective actions were identified during this field inspection.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101865	View of facility (view West); work in progress	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152212">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152212</a>
690101866	Off location flowline pin flagged; view South	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152213">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152213</a>